



MX1102A

HOBO ????/??/????????

????????

????????????????????

Important Information

??HOBOWare????????????Windows???HOBOnetconnect????????????
HOBOnetconnect????????????????????????????LI-COR Cloud® IoT ??????????
HOBOnetlink??? MX ?????



Compatible with
HOBOnetconnect® ????
LI-COR Cloud® MX ????

Supported Measurements

????, ??, ???? , ??

Features

- ????????????
- ?5??CO2????????????6??
- ?????HOBOnetconnect????????????
- ???????????
- ???NDIR CO2????????????
- ?????

What's in the box

- HOBO MX1102 CO2 ?????
- ??AA 1.5?????

Contact Us

Sales (8am to 5pm ET, Monday through Friday)

- Email sales@onsetcomp.com
- Call 1-508-759-9500
- In U.S. toll free 1-800-564-4377
- Fax 1-508-759-9100

Technical Support (8am to 5pm ET, Monday through Friday)

- Contact Product Support www.onsetcomp.com/support/contact
- Call 1-508-759-9500
- In U.S. toll free 1-877-564-4377

Onset Computer Corporation
470 MacArthur Boulevard
Bourne, MA 02532

HOBO
/
/
(MX1102A) Specifications

??	0°C?50°C (32????122???)
???	±0.21°C??0°C?50°C????????? (±0.38????32°?122°F?????????????)
??	25°C??0.024°C????????? (0.04????77?????????????)
??	????0.1°C (0.18??/?)

??	1% to 90% RH (non-condensing)
???	±2% from 20% to 80% typical to a maximum of ±4.5% including hysteresis at 25°C (77°F); below 20% and above 80% ±6% typical
??	0.01%
??	<1% per year typical

??	0 to 5,000 ppm
???	±50 ppm ±5% of reading at 25°C (77°F), less than 90% RH (non-condensing) and 1,013 mbar
????	15 seconds
??	Auto or manual to 400 ppm
???	<1% of FS
?????	0.13% of reading per mm Hg (corrected via user input for elevation/altitude)
??????	950 to 1,050 mbar (use Altitude Compensation for outside of this range)
??????	-305?5,486? (-1000?18000??)
????	Non-dispersive infrared (NDIR) absorption

??	?1?/?????12????90% (?2.2??/???????12????90%?)
????	1????1?/???????90% (?2.2??/???????1????90%)
????	?1?/?????1????90% (?2.2??/???????1????90%?)

